

POLY-CRETE® MD INSTALLATION TOOL LIST

This tool list is a comprehensive check list of the materials and tools needed for a Poly-Crete MD, MDB flooring system installation.

Items in **Bold** are mandatory

Surface Preparation:		
Scarifier	 4" Grinder	
Shotblaster	 Diamond Blades	
Adequate Vacuums	 Chipping Hammer	
Crack Chaser	 1 & 3" Chisels (for above)	
7" Grinder	 4" Brick Chisel	
Various Brooms	 Shovel	
Wheel Barrow		
Mixing Station:		
High Torque Mixer	 Mixing sticks	
6 gallon steel mixing pails	 Painters 5 in 1 tool	
4" Spiral Mixing Paddle	 Rags	
Dust Mask	 Surface thermometer	
Rags	 Rubber gloves	
Cardboard	 Extension Cords	
4-6 mil Polyethylene sheets	 Duct Tape	
Cart to move mix to Floor	 Garbage Bags	

Application Equipment:		
Cam Rake		Finish Trowels (4" wide)
15/16" Spike Roller		½" V notch Trowel
Rubber Gloves		Margin Trowels
2 gallon Broadcast Buckets		Cardboard
12" window squeegee		9" roller Frames
18" Roller Frames		3/8" nap Roller covers
Various Brooms		2" / 3" chip brushes
Cleaning Equipment:		
Solvent (xylene)		2" / 3" chip brushes
2 gal Pail		Rags
Safety		
Hard hats		Portable eye wash
Safety glasses		Fire Extinguisher (type B)
Respirators (if required)		Dust masks
Earplugs		MSDS sheets
Caution tape		Boots
Safety cones		Latex gloves
Leather gloves		
Concrete Repair		
Crack chaser		Carpenter level
Scrapers		Scrubber pads
Concrete saw		Sanding disks
Diamond blade		Zec wheels (16 grit)
Carbide blade		Chipping hammer
Diamond wheel $(7\frac{1}{2})^{2} - 24$ se	Straight edge	
Diamond wheel (4½" - 8 sec	ment)	